



GREG BELL Lieutenant Governor

## State of Utah

#### **DEPARTMENT OF NATURAL RESOURCES**

MICHAEL R. STYLER

Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA

Division Director

Company Rusty Netz

# **Inspection Report**

Permit Number:	C0070042
Inspection Type:	PARTIAL
Inspection Date:	Wednesday, August 17, 2011
Start Date/Time:	8/17/2011 11:30:00 AM
End Date/Time:	8/17/2011 2:00:00 PM
Last Inspection:	Wednesday, July 06, 2011

Inspector: Karl Houskeeper,

Weather: <u>Clear, Temp. 78 Deg. F.</u> InspectionID Report Number: <u>2834</u>

Accepted by: jhelfric 8/18/2011

Permitee: SUNNYSIDE COGENERATION ASSOCIATES
Operator: SUNNYSIDE COGENERATION ASSOCIATES

Site: STAR POINT REFUSE

Address: PO BOX 159, SUNNYSIDE UT 84539

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Λ.			. 4	A			-	
U	urr	en	IL.	А	Cr	eа	u	es

Total Permitted	152.93
Total Disturbed	152.93
Phase I	
Phase II	
Phase III	

Federal	Underground
State	Surface
County	Loadout
<b>✓</b> Fee	Processing
Other	<b>✓</b> Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Inspector's Signature:

Karl Houskeeper,

Inspector ID Number: 49



Date



OIL, GAS & MINING

Permit Number: C0070042 Inspection Type: PARTIAL

Inspection Date: Wednesday, August 17, 2011

Page 2 of 3

#### REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
  - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
  - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers	~		<b>✓</b>	
3.	Topsoil				
4.a	Hydrologic Balance: Diversions	✓		✓	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments				
4.c	Hydrologic Balance: Other Sediment Control Measures	✓		✓	
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments	<b>~</b>		~	
8.	Noncoal Waste				
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.8	Roads: Construction, Maintenance, Surfacing				
16.b	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
	Other	✓		✓	

Permit Number: C0070042 Inspection Type: PARTIAL

Inspection Date: Wednesday, August 17, 2011

Page 3 of 3

#### 2. Signs and Markers

The mine identification sign is located along side of the county road as you enter the permit area. The sign is in good repair and contains of the required information.

#### 4.a Hydrologic Balance: Diversions

The culverts located on the inlet and outlet of the pre sediment basin have been excavated and replaced with earthen material instead of refuse. The soil was compacted in lifts. This repair work was done because erosion had channeled to the sides of the culverts.

The diversion culvert located on the top of the refuse pile that drains the entire surface has been lowered so that a new excavation lift can begin.

### 4.c Hydrologic Balance: Other Sediment Control Measures

The ore sedimnet basins have been cleaned out.

#### 7. Coal Mine Waste, Refuse Piles, Impoundments

The surface of the refuse pile is being mined in lifts.

#### 22. Other

Many of the thistle plants on the permit area have been removed. One area at the entrance to the surface of the refuse pile remains.